Pr	operty is:	Single Family		Dup	olex	☑ Other □		
	5/2016	Sg.s . a,		Dup	,,,,,,			
		t to meet health and	safety	/ issue	s. T	ne City of Milwaukee, the Redevelopment Aut	hority, and their repres	entatives
ake no responsibility	for problems d	iscovered after the i	nspec	tion da	ate, o	for omissions through error or oversight. Th Block Grant or HOME programs.		
Exterior Condi			OI DY I		ucrai	block diant of Flowie programs.		
	equired Wo					Note/Comments		Cost
	ndscaping	n/a	✓	Yes		Self Help	\$	
Ste	eps/Handrails	n/a		Yes	V		\$	500.00
Se	rvice walks	n/a		Yes	V		\$	2,500.00
Fe	ncing	n/a	. 🗸	Yes			\$	
<u>Pa</u>	rking	n/a	✓	Yes			\$	
Re	taining walls	n/a		Yes	V		\$	4,500.00
Oth	ner	n/a		Yes			\$	
Oth	ner	n/a		Yes			\$	
Garage	ngles: repair	n/a	. 🗸	Yes			\$	
	ingles: Roof o			Yes			\$	
				Yes			\$ \$	
	ingles:Tear off						э \$	
	tters/downspo			Yes			·	
	shing	n/a		Yes			\$	
	ves	n/a		Yes			\$	
	ling	n/a		Yes	<u> </u>		\$	
<u>Do</u>		n/a		Yes			\$	
	ndows	n/a		Yes			\$	
Sla		n/a		Yes			\$	
<u>Pa</u>		n/a		Yes			<u>\$</u>	
	ectrical	n/a	. 🗸	Yes			\$	
Oth Porches	ner	n/a	. V	Yes			\$	
Ro	of	n/a	. 🗸	Yes			\$	
De	ck-upper	n/a		Yes			\$	
De	cklower	n/a		Yes	√	front porch	\$	1,400.00
Ste	eps/handrails	n/a		Yes	V		\$	500.00
Ce	iling	n/a	. 🗸	Yes			\$	
Gu	ardrails	n/a	. V	Yes			\$	
Str	uctural	n/a	. V	Yes			\$	
Pa	int	n/a	. \square	Yes	7		\$	800.00

n/a Yes v permit

\$

85.00

Other

House

Chimney	n/a ☐ Yes ✓		\$ 450.00
Shingles: repair	n/a ☐ Yes ☑	=	\$ 700.00
Shingles: Roof over existing	n/a ☑ Yes ☐		\$
Shingles:Tear off & re-roof	n/a ☑ Yes ☐		\$
Gutters/downspouts	n/a ☐ Yes ☑		\$ 420.00
Flashing	n/a ☑ Yes ☐		\$
Eaves	n/a ☐ Yes ✓		\$ 750.00
Siding	n/a ☐ Yes ☑		\$ 2,400.00
Storm Doors	n/a ✓ Yes 🗌		\$
Prime ("main") Doors	n/a ☐ Yes ☑		\$ 1,050.00
Storm Windows	n/a ☑ Yes ☐	_	\$ _
Prime ("main") Windows	n/a ☐ Yes ☑		\$ 1,550.00
Paint	n/a Yes 🗸		\$ 1,200.00
Foundation	n/a 🗸 Yes 🗌		\$
Electrical	n/a 🔽 Yes 🗌		\$
Other	n/a Yes 🗸	Drain or remove oil tank in basement	\$ 2,500.00
Other	n/a Yes	-	\$ _
Other	n/a Yes		\$
Other	n/a 🗌 Yes 🗌		\$

Exterior: Estimated Cost:* \$ 21,305.00

^{*}average contracted cost. Actual costs may vary. Self help will reduce the amount.

Interior Co	ndition Report							
	Unit: Entire unit (single family) Upper unit of duplex				Lower unit of duplex Other			
Mechanical	Required Work							
Heating	Repair/replace boiler	n/a ✓	Yes				\$	
	Repair radiation	n/a ☑	Yes				\$	
	Repair/replace furnace	n/a 🗆	Yes	<u> </u>			Ψ	3,080.00
			Yes	<u>v</u>			φ	500.00
	Repair ductwork Replace thermostat	n/a 🗌			-		э \$	100.00
		n/a	Yes		_		 \$	100.00
	Repair/replace grilles	n/a ✓	Yes		to a sum it			05.00
Electrical	Other	n/a 📙	Yes	✓	permit		\$	85.00
	Repair/replace receptacles	n/a 🔲	Yes	V			\$	500.00
	Repair/replace switches	n/a 🔲	Yes	V			\$	500.00
	Repair/replace fixtures	n/a 🔲	Yes	V			\$	500.00
	Install outlets and circuits	n/a ✓	Yes				\$	
	Install outlets and circuits	n/a ✓	Yes		_		\$	
	Install outlets and circuits	n/a 🗸	Yes				\$	
	Install outlets and circuits	n/a ✓	Yes				\$	
	Upgrade service	n/a 🗌	Yes	V			\$	2,100.00
	Other	n/a 🔲	Yes	V	permit		\$	85.00
	Other	n/a 🔲	Yes				\$	
Plumbing	Repair/replace kitchen sink	n/a □	Yes				\$	
	Repair/replace kitchen sink fauce		Yes				\$	
	Repair/replace tub	n/a 🗌	Yes				\$	·
	Repair/replace tub faucet	n/a 🔲	Yes				\$	
	Repair/replace toilet	n/a 🗌	Yes		_		Ψ \$	
	Repair/replace lavatory	n/a □	Yes				Ψ	
	Repair/replace lavatory faucet	n/a □					φ	
			Yes					
	Repair/replace wash tub	n/a	Yes				\$	
	Repair/replace wash tub faucet	n/a 🗌	Yes				\$	
	Other	n/a	Yes	_	permit		\$	85.00
	Repair drain/waste/vent piping	n/a 🔲	Yes				\$	600.00
	Repair water piping	n/a 🗌	Yes		<u></u>		\$	600.00
	Repair/replace water heater	n/a 🔲	Yes	✓	_		\$	1,300.00
	Kitchen	n/a 🔲	Yes		_		\$	1,750.00
	Bathroom	n/a 🔲	Yes	✓			\$	2,250.00

Windows						
	Replace broken glass	n/a ✓	Yes 🗌		\$	
_	Repair or replace sash	n/a ✓	Yes 🗌		\$	
Doors	Repair or replace doors	n/a 🔲	Yes 🗸		\$	380.00
	Repair or repl. locks/latches	n/a 🔲	Yes ✓	Self Help	\$	110.00
Walls/Ceilings	Repair or repl. @ defective	n/a 🔲	Yes 🗸		\$	750.00
Paint	Repair or repl. @ defective	n/a □	Yes ▽		\$	1,200.00
Fire Safety	Nepall of Tepl. @ defective	11/a	163 🗸		Ψ	1,200.00
i ile Salety	Install smoke/CO alarm:bsmt.	n/a 🔲	Yes 🗸	Self Help	\$	85.00
	Install smoke/CO alarm: 1st flr.	n/a 🔲	Yes 🗸	Self Help	\$	170.00
	Install smoke/CO alarm: 2nd flr.	n/a 🔽	Yes 🗌	Self Help	\$	
Handrails	Repair/replace defective	n/a 🔲	Yes ✓	Self Help	\$	250.00
Stairs	Repair defective	n/a ☑	Yes □		\$	
Floors	nepail delective	11/a [V]	165		Ψ	
Other	Repair defective	n/a 🔲	Yes ✓	7	\$	1,500.00
oo.		n/a 🔲	Yes 🗌		\$	
		n/a 🔲	Yes 🗌		\$	
		n/a 🔲	Yes _		\$	
		n/a 🗌	Yes 🗌		\$	

Interior Co	ndition Report								
	Unit: Entire unit (single family) Upper unit of duplex	□				Lower unit of duplex Other			
Mechanical Heating	Required Work								
ricating	Repair/replace boiler	n/a [√	Yes		_		\$	
	Repair radiation	n/a [✓	Yes		_		\$	
	Repair/replace furnace	n/a [Yes	V			 \$	3,080.00
	Repair ductwork	n/a [Yes	V			 \$	500.00
	Replace thermostat	n/a [Yes	V			 \$	100.00
	Repair/replace grilles	n/a [✓	Yes		_		 \$	
	Other	n/a [Yes	V	permit		\$	85.00
Electrical	Repair/replace receptacles	n/a [Yes	✓			\$	500.00
	Repair/replace switches	n/a [Yes	V			 \$	500.00
	Repair/replace fixtures	n/a [Yes	V			\$	500.00
	Install outlets and circuits	n/a [✓	Yes				\$	
	Install outlets and circuits	n/a [✓	Yes				\$	
	Install outlets and circuits	n/a [✓	Yes				\$	
	Install outlets and circuits	n/a [✓	Yes				\$	
	Upgrade service	n/a [Yes	V			\$	2,100.00
	Other	n/a [Yes	V	permit		\$	85.00
	Other	_n/a [Yes				\$	
Plumbing	Repair/replace kitchen sink	n/a [√	Yes				 \$	
	Repair/replace kitchen sink fauce	ein/a [Yes	V			 \$	350.00
	Repair/replace tub	n/a [✓	Yes				 \$	
	Repair/replace tub faucet	n/a [✓	Yes				\$	
	Repair/replace toilet	n/a [✓	Yes		_		 \$	
	Repair/replace lavatory	n/a [Yes	V	_		 \$	275.00
	Repair/replace lavatory faucet	n/a [Yes	V			 \$	315.00
	Repair/replace wash tub	n/a [✓	Yes				\$	
	Repair/replace wash tub faucet	n/a [✓	Yes				\$	
	Other	n/a [Yes	V	permit		 \$	85.00
	Repair drain/waste/vent piping	n/a [Yes	V			\$	400.00
	Repair water piping	n/a [Yes	✓			 \$	310.00
	Repair/replace water heater	n/a [Yes	√			 \$	1,300.00
	Other	n/a [Yes				\$	
	Other	n/a [Yes			_	\$	

Inspected by:	Jeff Sporer					*average contracted cost. Actual costs may vary. Self help will reduce Date: 8/2/2016	the amoun	t.
						Total Exterior and Interior Cost:*	\$	52,230.00
						Interior: Estimated Cost:	\$	30,925.00
		n/a [Yes			\$	
		n/a [Yes			\$	
		n/a [Yes			\$	
Other		n/a [Yes			\$	
Floors	Repair defective	n/a [✓	Yes			\$	
Stairs	Repair defective	n/a [√	Yes			\$	
	Repair/replace defective	n/a [√	Yes		Self Help	\$	
Handrails	Install smoke/CO alarm: 2nd flr.	n/a [Yes	V	Self Help	\$	170.00
	Install smoke/CO alarm: 1st flr.	n/a [✓	Yes		Self Help	\$	
The Salety	Install smoke/CO alarm:bsmt.	n/a [✓	Yes		Self Help	\$	
Fire Safety	Repair or repl. @ defective	n/a [Yes	✓	~	\$	800.00
Paint				.,	_		_	
Walls/Ceilings	Repair or repl. @ defective	n/a _[Yes	V		\$	500.00
	Repair or repl. locks/latches	n/a _[Yes	V	Self Help	\$	110.00
Doors	Repair or replace doors	n/a _[Yes	V		\$	380.00
D	Repair or replace sash	n/a _	√	Yes			\$	
	Replace broken glass	n/a _[√	Yes			\$	
Windows								

Self Help

Work listed as "self help" means the cost estimate includes only the cost of the materials, not labor or equipment.

Important Information Regarding Permits

All plumbing, heating, electrical, and structural repairs require permits before work can start. Permits are also required for other work such as new siding, new drywall, new doors. Permits are obtained at the Development Center located on the first floor of 809 N. Broadway.

Licensed contractors must do the above work, although owner occupants may be eligible to do maintenance work and structural/carpentry repairs.

Owner occupants may be eligible to do plumbing work on the unit they live in, but check with the plumbing inspector first.

Generally, minor carpentry repairs, plaster patching, and painting do not require permits.

Anyone disturbing painted surfaces must assume they contain lead paint if the home was built before 1978. Contractors must be licensed to do lead abatement and must obtain a permit. Permits are obtained from the Health Department, located at 7630 W. Mill Road.